## BENGAL ENGINEERING AND SCIENCE UNIVERSITY, SHIBPUR B. E. 4<sup>th</sup> Semester (MET), Semester Examination, April/May 2013

## Introduction to Physical Metallurgy (MT 401)

Full Marks: 70 Time: 3 hrs

## Answer any SEVEN questions.

Use single answer-script for answering of all questions.

Figures on the right-hand side indicate full marks.

- **1.** (a) Describe the principle of temperature measurement by thermoelectric method.
  - (b) Name the principal thermocouples with their chemical composition.
  - (c) How is a thermocouple calibrated?

[4+3+3]

- 2. (a) Draw the Fe-Fe<sub>3</sub>C equilibrium diagram with proper labeling.
  - (b) Write down the phase transformation reactions encountered in the system indicating the temperature and composition of their occurrence.
  - (c) What is 'transformed' ledeburite?

[5+3+2]

- 3. (a) Indicate the annealing and normalizing temperature ranges in the relevant portion of the Fe-Fe<sub>3</sub>C diagram and justify the choice.
  - (b) Why is tempering necessary after hardening of steel? What structural changes occur on tempering?

[5+5]

- **4.** Differentiate between:
  - (a) Process annealing and spheroidizing annealing
  - (b) Strain hardening and precipitation hardening

[5+2]

- **5.** (a) Explain the terms *resolving power* of a lens and *empty magnification*.
  - (b) Explain with line diagrams the *bright field* and *dark field* illumination in optical microscopy.

[4+6]

## BENGAL ENGINEERING AND SCIENCE UNIVERSITY, SHIBPUR B. E. 4<sup>th</sup> Semester (MET), Semester Examination, April/May 2013

- 6. (a) Discuss Hume Rothery's rules of solid solutions citing examples.
  - (b) Explain the order-disorder phenomenon in solid solutions.

[7+3]

- 7. (a) Differentiate between edge dislocation and screw dislocation.
  - (b) With example discuss Kirkendal effect.

[5+5]

- 8. (a) Derive Fick's second law of diffusion.
  - (b) A hydrocarbon gas with C concentration of 1.0 wt. % is used for carburization of 0.2 wt. % plain C steel. Calculate how long it would take at 1000 °C to reach a C content of 0.6 wt.% at a distance of 1 mm from the surface.

Given: 
$$D_{c \text{ in } \gamma\text{-Fe at } 1273 \text{ K}} = 2.98 \times 10^{-11} \text{ m}^2/\text{s}$$

$$Z = 0.40 \qquad \text{erf}(z) = 0.4284$$

$$Z = 0.45 \qquad \text{erf}(z) = 0.4755$$

$$Z = 0.50 \qquad \text{erf}(z) = 0.5205$$

$$Z = 0.55 \qquad \text{erf}(z) = 0.5633$$

[5+5]

- **9.** (a) Differentiate between *steady-state* and *non steady-state diffusion* with the help of appropriate diagram(s).
  - (b) Prove that interstitial diffusion is much faster than the substitutional diffusion.
  - (c) Briefly explain the ring mechanism of substitutional diffusion.

[3+5+2]

- 10. (a) Classify solids based on atomic agreement.
  - (b) Calculate the (theoretical) density of copper if lattice parameter, a = 3.61 A, and the atomic weight of copper is 63.5.
  - (c) Discuss stacking fault in FCC crystal structure.
  - (d) Draw [121] and (211) in a cubic unit cell.

[2+2+3+3]